



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangertter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 9/18/87
4:00 pm to 5:00 pm

Permittee and/or Operators Name: Summit Minerals, Inc.
Business Address: 221 West 2100 South, Salt Lake City, Utah 84115
Mine Name: Summit Minerals #1 Permit Number: INA/043/001
Type of Mining Activity: Underground Surface Other
County: Summit
Company Official (s): none
State Official(s): Rick Summers
Partial: Complete: Date of Last Inspection: 6/11/87
Weather Conditions: Clear
Acreage: Permitted 0 Disturbed 16 Regraded Seeded Bonded 16
Enforcement Action: None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	(X)	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	(X)	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	(X)	()
12. BACKFILLING AND GRADING	()	()	(X)	()
13. REVEGETATION	()	()	(X)	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	(X)	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	(X)
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION 9/21/87

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS


The operator responded to the Division's Findings Document and Technical Analysis with concerns relative to several stipulations. The Division is currently preparing a response to those concerns.

16d. Roads - Maintenance

During the inspection, Dale (contacted maintenance man for Summit Minerals) was onsite repairing the berm on the access road to the site. He replaced several straw bales along the access road to insure adequate treatment of road drainage.

Copy of this Report:

Mailed to: John Kathman - OSM Jack Higgins - Summit Mineral, Inc.
Given to: Joe Helfrich - DOGM

Inspectors Signature and Number:  #15 Date: 9/25/87