

6-9-89
7130

0003

sa
jch



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: June 2, 1989
Noon to 2:30 p.m.

Permittee and/or Operators Name: Summit Minerals, Inc.
Business Address: 221 West 2100 South, Salt Lake City, Utah 84115
Mine Name: Summit Minerals #1 Permit Number: INA/043/001
Type of Mining Activity: Underground XXX Surface Other _____
County: Summit
Company Official (s): None
State Official(s): Harold G. Sandbeck, Joe Helfrich and Daron Haddock
Partial: _____ Complete: XXX Date of Last Inspection: March 16, 1989
Weather Conditions: Clear and warm
Acreage: Permitted 0 Disturbed 16 Regraded _____ Seeded _____ Bonded 16
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|-------|-------|-------|----------|
| 1. PERMITS | () | (XX) | () | (XX) |
| 2. SIGNS AND MARKERS | (XX) | () | () | () |
| 3. TOPSOIL | () | () | (XX) | () |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. STREAM CHANNEL DIVERSIONS | () | () | (XX) | () |
| b. DIVERSIONS | (XX) | () | () | () |
| c. SEDIMENT PONDS AND IMPOUNDMENTS | (XX) | () | () | () |
| d. OTHER SEDIMENT CONTROL MEASURES | (XX) | () | () | () |
| e. SURFACE AND GROUNDWATER MONITORING | (XX) | () | () | () |
| f. EFFLUENT LIMITATIONS | (XX) | () | () | () |
| 5. EXPLOSIVES | () | () | (XX) | () |
| 6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL | () | () | (XX) | () |
| 7. COAL PROCESSING WASTE | () | () | (XX) | () |
| 8. NONCOAL WASTE | (XX) | () | () | () |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | (XX) | () | () | () |
| 10. SLIDES AND OTHER DAMAGE | () | () | (XX) | () |
| 11. CONTEMPORANEOUS RECLAMATION | () | () | (XX) | () |
| 12. BACKFILLING AND GRADING | () | () | (XX) | () |
| 13. REVEGETATION | () | () | (XX) | () |
| 14. SUBSIDENCE CONTROL | () | () | (XX) | () |
| 15. CESSATION OF OPERATIONS | () | () | (XX) | () |
| 16. ROADS | | | | |
| a. CONSTRUCTION | () | () | (XX) | () |
| b. DRAINAGE CONTROLS | (XX) | () | () | () |
| c. SURFACING | (XX) | () | () | () |
| d. MAINTENANCE | (XX) | () | () | () |
| 17. OTHER TRANSPORTATION FACILITIES | () | () | (XX) | () |
| 18. SUPPORT FACILITIES UTILITY INSTALLATIONS | (XX) | () | () | () |

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION June 2, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. The operator was not available to accompany the undersigned inspector on this complete. No evidence of mining or mining related activities were noted on the site.

1. Permits. Summit Minerals has been denied a permit. Forfeiture of the reclamation bond is currently ongoing and the reader is referred to the Division correspondence files for additional information.

Copy of this Report:

Mailed to: Jack Higgins(Summit Minerals), Price Office & Brian Smith(OSM)
Given to: Sue Linner and Joe Helfrich, - DOGM

Inspectors Signature and Number: *Harold J. Asenaker* #27 Date: June 2, 1989