

4-3-89  
7:30

0004



# State of Utah INSPECTION REPORT

*Jch scl*

Norman H. Bangertor  
Governor

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
INSPECTION DATE & TIME: March 16, 1989  
11:30 a.m. to 1:00 p.m.

Permittee and/or Operators Name: Summit Minerals, Inc.

Business Address: 221 West 2100 South, Salt Lake City, Utah 84115

Mine Name: Summit Minerals #1 Permit Number: INA/043/001

Type of Mining Activity: Underground  Surface  Other

County: Summit

Company Official (s): None

State Official(s): Harold G. Sandbeck

Partial:  Complete:  Date of Last Inspection: December 2, 1989

Weather Conditions: Clear and cool

Acreage: Permitted 0 Disturbed 16 Regraded  Seeded  Bonded 16

Enforcement Action: None

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	(XX )	( )	(XX )
2. SIGNS AND MARKERS	(XX )	( )	( )	( )
3. TOPSOIL	( )	( )	(XX )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	(XX )	( )
b. DIVERSIONS	(XX )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	(XX )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	(XX )	( )	( )	( )
f. EFFLUENT LIMITATIONS	(XX )	( )	( )	( )
5. EXPLOSIVES	( )	( )	(XX )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	(XX )	( )
7. COAL PROCESSING WASTE	( )	( )	(XX )	( )
8. NONCOAL WASTE	(XX )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(XX )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	(XX )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	(XX )	( )
12. BACKFILLING AND GRADING	( )	( )	(XX )	( )
13. REVEGETATION	( )	( )	(XX )	( )
14. SUBSIDENCE CONTROL	( )	( )	(XX )	( )
15. CESSATION OF OPERATIONS	( )	( )	(XX )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	(XX )	( )
b. DRAINAGE CONTROLS	(XX )	( )	( )	( )
c. SURFACING	(XX )	( )	( )	( )
d. MAINTENANCE	(XX )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	(XX )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(XX )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION March 16, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. The operator was not available to accompany the undersigned inspector on this complete. No evidence of mining or mining related activities were noted on the site.

1. Permits. Summit Minerals has been denied a permit. Forfeiture of the reclamation bond is currently ongoing and the reader is referred to the Division correspondence files for additional information.

Copy of this Report:

Mailed to: Jack Higgins (Summit Minerals), Price Office & Brian Smith (OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Harold J. Jendrich* #27 Date: 3/28/89