



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

DRZ
gh

INSPECTION REPORT

INSPECTION DATE & TIME: June 11, 1991
10:30 A. M. - 1:30 P. M.

Permittee and/or Operator's Name: Summit Minerals, Inc.
Business Address: 221 W. 2100 S., Salt Lake City, UT 84115
Phone: (801) 486-1861
Mine Name: Summit #1 Permit Number: INA/043/001
Type of Mining Activity: Underground X Surface Other
County: Summit Company Official(s): None Present
State Officials(s): Priscilla Burton and Paul Baker
Federal Official(s): None
Partial: Complete X Date of last Inspection: 02/27/91
Weather Conditions: Clear, sunshine, 70's.
Acreage: Permitted 0 Disturbed 16 Regraded
Seeded Bonded 16 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	(X)	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	(X)	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	(X)
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	(X)	()	()	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	(X)
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	(X)	()
12. BACKFILLING AND GRADING	()	()	(X)	()
13. REVEGETATION	()	()	(X)	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	(X)	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	(X)

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION: 06/11/91

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENT:

There was no sign of any recent activity at the site. We encountered William Boyer, surface owner of the adjacent cropland, who uses the mine access road for farm/irrigation access.

1. PERMITS

We performed an AVS check of the permit and mine I.D. signs. The information provided on the sign agreed with that in the permit. However, the permit was never approved. Map S1 1008, Existing Contour, is the map that depicts the surface conditions at the site.

4.e. SURFACE AND GROUNDWATER MONITORING

We located four uncapped cast iron casings, 5.5" diameter. The jagged edges of these casings extend 5" above the surface. These casings are located just west of the main office building. The other two wells were sited by the concrete tipple area, near the machine shop. Other inspectors indicate that the casings are part of an underground diesel storage facility or a cistern.

9. PROTECTION OF WILDLIFE

There is a (red tailed?) hawk nest in a dead cottonwood next to Chalk Creek. The mated pair and three nestlings were sited. This nest is not identified in either the Summit Minerals or Boyer Mine plan. We also saw an owl just outside the perimeter of the disturbed area.

18. SUPPORT FACILITIES

All of the buildings were unlocked with some papers and other refuse strewn around inside.

Copy of this Report:

Mailed to: Brian Smith(OSM); Jack Higgins (Summit)

Given to: Daron Haddock, DOGM; Joe Helfrich, DOGM

Inspector's Signature & Number: *Paula Banta* # 37
Date: June 14, 1991