

10-19-88

2022

LOG



UTAH
NATURAL RESOURCES
Oil, Gas & Mining

0020

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

NO. N 88-27-6-3

notice of violation

To the following Permittee or Operator:

Name Summit Coal Company

Mine Boyer Mine Surface Underground Other

County Summit State Utah Telephone 336-5514

Mailing Address P.O. Box 646, Coalville, UT 84017

State Permit No. ACT/043/008

Ownership Category State Federal Fee Mixed

Date of inspection October 17, 1988, 19 88

Time of inspection 1:00 a.m. p.m. to 5:00 a.m. p.m.

Operator Name (other than Permittee) Jack Blongquist

Mailing Address Same As Above

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause; if a request is made within a reasonable time before the end of abatement period.

Date of service/mailing October 17, 1988 Time of service/mailing 5:00 a.m. p.m.

William C Blongquist
Permittee/Operator representative

Pres.
Title

William C Blongquist
Signature

Harold G. Sandbeck
Division of Oil, Gas & Mining representative

Reclamation Inspector
Title

Harold G. Sandbeck
Signature

#27
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



7022

NOTICE OF VIOLATION NO. N 88-27-6-3

Violation No. 1 of 3

Nature of violation

Failure to finish culvert installation (VD-1) as required
per field amendment ACT/043/008-88E.

Provisions of act, regulations or permit violated

UMC 771.19

Portion of operation to which notice applies

VD-1 culvert outlet.

Remedial action required (including any interim steps)

Complete culvert installation in VD-1 to county road
right of way (approx. 40 additional feet). Operator is reminded
to also install the energy dissipator per field amendment
ACT/043/008-88E.

Abatement time (including interim steps)

November 15, 1988 at 5:00 PM.



7022

NOTICE OF VIOLATION NO. N 88-27-6-3

Violation No. 2 of 3

Nature of violation

Failure to conduct vegetation sampling and submit reports
by September 2, 1988 as per Division directive dated June 15, 1988.

Provisions of act, regulations or permit violated

UMC 771.19

Portion of operation to which notice applies

Vegetation reference area.

Remedial action required (including any interim steps)

None

Abatement time (including interim steps)

None



NOTICE OF VIOLATION NO. N 88-27-6-3

Violation No. 3 of 3

Nature of violation

Failure to collect water samples for the month of
September, 1988.

Provisions of act, regulations or permit violated

UMC 771.19

Portion of operation to which notice applies

Sample Sites @ SS-5, SS-6, Old well, Boyer and Morbey wells,
New Well, Mine Water.

Remedial action required (including any interim steps)

None

Abatement time (including interim steps)

No abatement possible. However, operator is required to follow
his approved plan.