

0030



Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

September 12, 1988

*File Boyer Mine
1043/008 #2*

TO: File

FROM: David W. Darby, Geologist *DWD*

RE: Compliance to Stipulation UMC 817.121-.126-DD, Summit Coal Company, Inc., Boyer Mine, CEP/043/002, Summit County, Utah, Folder #2

Synopsis

Page 5 of the Technical Review Document of May 15, 1988 (State Permit and Decision Document) outlines subsidence control deficiencies in Summit Coal Company' Mine Permit Application.

On June 15, 1987 Summit Coal Company (SCC) submitted the required information to address and comply with the conditions outlined in Stipulation UMC 817.121-.126-DD (See Letter to Mr. Richard Blonquist from Dianne Nielson May 15, 1987) for subsidence monitoring and ground control.

Recommendations

Summit Coal Company has met the requirements of Regulations UMC 817.121-.126. These stipulations have been fully addressed and the information can be incorporated in the Mining and Reclamation Plan.

dwd
cc: R. Harden
S. Linner
R. Summers

1565R-15