



NOV

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Jan. 14, 1988  
9:00 a.m. to 11:30 a.m.

Permittee and/or Operators Name: Summit Coal Co.  
 Business Address: P.O. Box 646, Coalville, Utah 84017  
 Mine Name: Boyer Mine Permit Number: ACT/043/008  
 Type of Mining Activity: Underground  Surface  Other   
 County: Summit  
 Company Official (s): Jack Blonquist  
 State Official(s): Rick Summers  
 Partial:  Complete:  Date of Last Inspection: 12/18/87  
 Weather Conditions: overcast  
 Acreage: Permitted 170 Disturbed 5.5 Regraded  Seeded  Bonded 5.5  
 Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( X )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( X )	( )	( )	( X )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( X )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( X )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( X )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/043/002

DATE OF INSPECTION 1/14/88

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

The operator submitted a response to the stipulation review on 12/18/88. Included in this submittal were plans for a proposed temporary and a final disposal area for the coal waste material. The results of the analysis for two samples of the waste rock material were submitted to the Division on 12/23/88. These are currently under review by the Division staff.

4. HYDROLOGIC BALANCE: c. SEDIMENT PONDS AND IMPOUNDMENTS

Inspection of records at the office verified the sediment pond has been inspected and the appropriate report completed by a registered professional engineer for the fourth quarter of 1987. Pond was inspected on 11/14/87.

4. HYDROLOGIC BALANCE: d. OTHER SEDIMENT CONTROL MEASURES

The operator has grouted the catch basin located at the base of the entrance road as requested during the December inspection. Mr. Blonquist stated the repair was completed the day following the December inspection (12/19/87).

4. HYDROLOGIC BALANCE: e. SURFACE AND GROUNDWATER MONITORING

We discussed the responsibility for continuing the water monitoring program at the site. In April of this year, SOAP funded monitoring will be completed for the surface water monitoring sites. At that time, it will be the operator's responsibility to conduct the operational monitoring program for the site. Monitoring of the well at the site (new well) will continue for approximately one more year using SOAP funds.

16. ROADS b. DRAINAGE

The operator was informed that snow removed from the site should be stored in a location that would report to the sedimentation pond during melt.

Copy of this Report:

Mailed to: Jack Blonquist, John Kathman (OSM)

Given to: NOV File, Sue Linner, Joe Helfrich

Inspectors Signature and Number: R. Summers #15 <sup>RS</sup> Date: 1/14/88