

0003



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: September 7, 1989
12:30 p.m. to 2:00 p.m.

Permittee and/or Operators Name: Summit Coal Company
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: INA/043/008
Type of Mining Activity: Underground Surface Other
County: Summit
Company Official (s): None
State Official(s): Harold G. Sandbeck
Partial: Complete: Date of Last Inspection: June 15, 1989
Weather Conditions: Clear and hot
Acreage: Permitted 170 Disturbed 5.5 Regraded Seeded Bonded 5.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	(XX)	()	(XX)
2. SIGNS AND MARKERS	(XX)	()	()	()
3. TOPSOIL	(XX)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(XX)	()	()	()
b. DIVERSIONS	()	(XX)	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(XX)	()	()	()
f. EFFLUENT LIMITATIONS	(XX)	()	()	()
5. EXPLOSIVES	()	()	(XX)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	(XX)	()	(XX)
7. COAL PROCESSING WASTE	()	()	(XX)	()
8. NONCOAL WASTE	(XX)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(XX)	()	()	()
10. SLIDES AND OTHER DAMAGE	(XX)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(XX)	()	()	()
12. BACKFILLING AND GRADING	(XX)	()	()	()
13. REVEGETATION	()	(XX)	()	()
14. SUBSIDENCE CONTROL	(XX)	()	()	()
15. CESSATION OF OPERATIONS	(XX)	()	()	()
16. ROADS				
a. CONSTRUCTION	(XX)	()	()	()
b. DRAINAGE CONTROLS	(XX)	()	()	()
c. SURFACING	(XX)	()	()	()
d. MAINTENANCE	(XX)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(XX)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(XX)	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/008

DATE OF INSPECTION 9/7/89

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. A complete inspection was conducted without company representation. On October 13, 1988, the mine ceased operations. During the field inspection, no mine related activity was noted except that both mine access gates were open. Ground conditions were dry.

1. Permits.

On August 4, 1989, the Boyer Mine permit, ACT/043/008, was revoked. At this time the Division has initiated bond forfeiture activities with the intent of reclaiming this mine site when funds become available.

6. Disposal of Development Waste and Spoil.

As noted in the June 15, 1989 inspection report, the toe of the temporary waste coal pile adjacent to the truck scale had been burning. The burning coal was subsequently extinguished by the operator. On June 16, 1989, the Division posted three danger signs warning the public of the danger of an open mine and the burning coal pile.

Copy of this Report:

Mailed to: Jack Blonquist (Manager), Price Office and Brian Smith (OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Harold J. Jam* #27 Date: 9/8/89