

7022
3-2-89

0024



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
INSPECTION REPORT

SA
JCH

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION DATE & TIME: February 16, 1989
10 a.m. to 2 p.m.

Permittee and/or Operators Name: Summit Coal Company
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: ACT/043/008
Type of Mining Activity: Underground Surface Other
County: Summit
Company Official (s): Jack Blonquist
State Official(s): Harold G. Sandbeck
Partial: Complete: Date of Last Inspection: January 16, 1989
Weather Conditions: Clear and cold
Acreage: Permitted 170 Disturbed 5.5 Regraded Seeded Bonded 5.5
Enforcement Action: N89-27-1-2 (See #1 and #4e.)

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	(XX)	()	(XX)
2. SIGNS AND MARKERS	(XX)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	(XX)	()	(XX)
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/043/008

DATE OF INSPECTION 02/16/89

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. A partial inspection was conducted with Jack Blonquist. During the field inspection, no mine related activity was noted. The site was covered with two to three feet of snow.

1. Permits.

N88-27-7-4, 1 of 4 was modified to give the operator additional time to retrieve the above mentioned certifications from the contracted engineer. Court action may be necessary. The new abatement date is March 2, 1989. For additional information, please refer to the January 16, 1989 inspection report.

N88-27-8-1 had been issued on December 16, 1989 for failure to respond to the conditional approval letter dated September 30, 1988. The abatement date is March 16, 1989.

N89-27-1-2, 1 of 2 was issued on February 16, 1989 for failure to submit the UD-1 culvert revisions and certifications as required by the field amendment ACT/043/008-88E. The abatement date is March 16, 1989.

UPDES (Utah Pollutant Discharge Elimination System)

The operator request for a UPDES permit was granted. The UPDES permit number is UTG040001 which became effective February 1, 1989. The permit expires on April 30, 1993. This permit requires the operator to monitor for boron once per quarter in addition to the other parameters.

4. Hydrologic Balance:

e. Surface and Groundwater Monitoring.

N89-27-1-2, 2 of 2 was issued for failure to collect water samples for the months of November and December of 1988 and January and February of 1989. Since there is no remedial action possible, this violation was terminated on the same day of issuance. However, the operator is required to follow his approved plan.

Copy of this Report:

Mailed to: Jack Blonquist (Manager), Price Office and Brian Smith (OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Harold J. Fern* #27 Date: 02/17/89