



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: September 12, 1990
11:00 am to 1:00 pm

Permittee and/or Operators Name: Summit Coal Company
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: INA/043/008
Type of Mining Activity: Underground Surface Other
County: Summit County
Company Official (s): None
State Official(s): randy Harden, Joe Helfrich, Dave Darby
Partial: Complete: Date of Last Inspection: June 6, 1990
Weather Conditions: Clear, Warm
Acreage: Permitted 170 Disturbed 5.5 Regraded Seeded Bonded 5.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	(X)	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	(X)	()	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	(X)	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	(X)	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	(X)	()	()	()
15. CESSATION OF OPERATIONS	(X)	()	()	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/008

DATE OF INSPECTION September 12, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

The permit for the Boyer Mine was revoked on October 13, 1988. No mining related activity has occurred on that site since that date. Since the time of the last inspection, the operator has removed much of the mining equipment from the property.

Bond forfeiture proceedings are under way with the real property used for a collateral bond with the Division. In the interim, the Division has contracted reclamation work to commence at the Boyer Mine. The initial phase of the reclamation work to be conducted this fall will consist only of the backfilling of the portals and the installation of water bars in both access roads to the site to control erosion.

Upon receipt of funds from the eventual sale of the real property used as collateral, it is anticipated that complete reclamation of the site will occur by next fall.

In conjunction with the inspection, the Division held a contractor's on site meeting as part of the bidding process for closure of the portals. Since the date of the field inspection, the bid has been let and actual reclamation construction on the site for the closure of the portals will occur starting October 1, 1990.

In general, the site appears to be in fair condition especially in consideration of the amount of time that the mine has remained idle. Due to the close proximity to the road and the high probability for vandalism, the Division has made closure of the portals a priority.

Copy of this Report:

Mailed to: Brian Smith - OSM

Given to: Joe Helfrich - DOGM, Daron Haddock - DOGM

Inspectors Signature and Number: #13



Date: September 28, 1990