

7022



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

LK
Jan

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: March 2, 1990
8:30 a.m. to 11:30 a.m.

Permittee and/or Operators Name: Summit Coal Company
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: INA/043/008
Type of Mining Activity: Underground XXX Surface Other _____
County: Summit
Company Official (s): None
State Official(s): Harold G. Sandbeck
Partial: _____ Complete: XXX Date of Last Inspection: 12/8/89
Weather Conditions: Clear and cold
Acreage: Permitted 170 Disturbed 5.5 Regraded _____ Seeded _____ Bonded 5.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	(XX)	()	(XX)
2. SIGNS AND MARKERS	(XX)	()	()	()
3. TOPSOIL	(XX)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(XX)	()	()	()
b. DIVERSIONS	()	(XX)	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(XX)	()	()	()
f. EFFLUENT LIMITATIONS	(XX)	()	()	()
5. EXPLOSIVES	()	()	(XX)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	(XX)	()	(XX)
7. COAL PROCESSING WASTE	()	()	(XX)	()
8. NONCOAL WASTE	(XX)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(XX)	()	()	()
10. SLIDES AND OTHER DAMAGE	(XX)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(XX)	()	()	()
12. BACKFILLING AND GRADING	(XX)	()	()	()
13. REVEGETATION	()	(XX)	()	()
14. SUBSIDENCE CONTROL	(XX)	()	()	()
15. CESSATION OF OPERATIONS	(XX)	()	()	()
16. ROADS				
a. CONSTRUCTION	(XX)	()	()	()
b. DRAINAGE CONTROLS	(XX)	()	()	()
c. SURFACING	(XX)	()	()	()
d. MAINTENANCE	(XX)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(XX)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(XX)	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/008

DATE OF INSPECTION 3/2/90

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments.

A complete inspection was conducted without company representation. On October 13, 1988, the mine ceased operations. No mine related activity was noted and ground conditions were extremely muddy.

Mining equipment is in the process of being removed from the Boyer mine site by Star Resources. The removal of this equipment is in accordance with bankruptcy court proceedings. MSHA is actively involved in the safe removal of the equipment underground. The undersigned inspector informed Ron Housekeeper, Rick Housekeeper and Bud Housekeeper (representatives of Star Resources) to protect the environmental controls such as ponds, ditches, berms, straw bales etc. The Housekeepers are aware that surface impacts must be minimized.

1. Permits.

On August 4, 1989, the Boyer Mine permit, ACT/043/008, was revoked. At this time the Division has initiated bond forfeiture activities with the intent of reclaiming this mine site when funds become available.

6. Disposal of Development Waste and Spoil.

The gob material was inspected and appears stable. No signs of burning coal was noted.

Copy of this Report:

Mailed to: Jack Blonquist (Manager), Price Office and Brian Smith (OSM)
Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Harold J. Amos* #27 Date: 3/5/90