

0013



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

GA *DRH*

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: January 26, 1991
1:00 pm to 4:00 pm

Permittee and/or Operators Name: Summit Coal Company
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: INA/043/008
Type of Mining Activity: Underground X Surface Other
County: Summit
Company Official (s): None
State Official(s): David W. Darby
Partial: XX Complete: Date of Last Inspection: Dec. 18, 1990
Weather Conditions: Cold, clear with snow on the ground
Acreage: Permitted 170 Disturbed 5.5 Regraded Seeded Bonded 5.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	(X)
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	(X)	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/008

DATE OF INSPECTION: 01-26-91

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit

There has been no activity at the minesite since the last inspection. Tracks in the snow indicated that no one had been at the site since the last snow storm which occurred at the first part of January. Several deer have moved down onto the minesite for the winter. Evidently, they find the coal refuse piles a good bedding area, because the snow has sublimated from the pile and heat is both absorbed and radiated by the refuse.

4. Hydrologic Balance

The inspection had revealed no runoff had left the site and there was no water stored in the sedimentation pond. The snow on the ground still has not melted to contribute runoff or muddy conditions.


12. Backfilling and Grading

The fill material in the portals was checked to see if any settling has occurred. The first portal showed sign that the fill material had settled about 12 to 14 inches in the front part of the entry to a distance of about 12 feet into the entry. It could not be determined if the settling had extended further due to the slope of the entry. The other two portals did not show signs of settling. The site should be examined this spring to determine if the fill material should be compacted against the roof of the entry.

Copy of this Report:

Mailed to: Brian Smith-OSM, PFO

Given to: Daron Hadock-DOGM, Joe Helfrich-DOGM

Inspectors Signature & Number:  #18 Date: 02-07-91