
CRANDALL CANYON
LITTLE BEAR CANYON
MILL FORK CANYON
COAL LEASE BOUNDARY
OUTCROP
LEAMASTER MINE
BASE OF SLOPES TO HIAWATHA SEAM
LOC 1
HC-3 3.6'
HC-4 5.5'
DH-2-76A 5.3'
HCD-1 4.0'
HC-5 6.5'
HCD-2 6.8
HC-1 5.5'
DH-10 4.4'
DH-9 6.0'
DH-7 5.6'
DH-8 5.6' (1.0' RECOVERED)
DH-12 7.4' (1.4 RECOVERED) (OXYDIZED) (E-LOG SHOWS 6.5')
MC-4-6 6.4' (5.5 RECOVERED)
MC-4-7 6.2' (4.7' RECOVERED)
MC-4-8 5.2'
MC-4-1 4.5' (NO RECOVERY)
MC-4-5 4.5' (2.5 RECOVERED)
MC-4-4 4.3' (3.3 RECOVERED)
MC-4-3 4.2' (2.2 RECOVERED)
MC-4-2 4.7' (OXIDIZED TOP) (3.1' RECOVERED)
DH-2A
DH-4 6.1' (OXIDIZED) (4.5' RECOVERED)
DH-6 4.5' (OXIDIZED LOWER 2.0')
DH-5 5.4' (OXIDIZED IN LOWER PART) (4.0' RECOVERED)
DH-1 (3.5' BURNT) (2.0' RECOVERED)
3.0' burnt omit
N
LEGEND
HCD-1 DRILL HOLES
COAL LEASE BOUNDARY
OVERBURDEN & UNDERBURDEN SAMPLE LOCATIONS
FAULTS
OUTCROP
OXIDIZED & BURNED COAL LINE
5' CONTOUR INTERVALS = 1'
BEAVER CREEK COAL COMPANY
No. 4 MINE AREA—HUNTINGTON
Emery County, Utah
ISOPACH MAP
HIAWATHA SEAM
Prepared A. Papp
Scale 1" = 500'
Department R.D.G./Exploration
Date Oct. 1981
Drawn by F.S.
PLATE 6-3