
Photographed in 1992
VIEW TO SOUTH FROM NORTH RILDA RIDGE
OCT 94
MAR 95
APR 95
AUG 95
SEP 95
DEC 95
JAN 96
OCT 95
NOV 95
JUL 96
DEC 96
JUN 96
MAY 96
OCT 96
APR 96
MAR 96
CASTLEGATE SANDSTONE OUTCROP
Photographed in 1997
VIEW TO SOUTH FROM NORTH RILDA RIDGE
Note: Longwall mining under this Castlegate Sandstone outcrop began in October, 1994 and ended in December, 1996. Individual mining months under each portion of the Castlegate Sandstone outcrop are shown.
Mining and Subsi
Rock Rolls
Surface Tension


Photographed in 1992
VIEW TO SOUTH FROM NORTH RILDA RIDGE
OCT 94
MAR 95
APR 95
AUG 95
SEP 95
DEC 95
JAN 96
OCT 95
NOV 95
CASTLEGATE SANDSTONE OUTCROP
CASTLEGATE SANDSTONE OUTCROP
Photographed in 1997
VIEW TO SOUTH FROM NORTH RILDA RIDGE
Note: Longwall mining under this Castlegate Sandstone outcrop began in October, 1994 and ended in December, 1996. Individual mining months under each portion of the Castlegate Sandstone outcrop are shown.