

01222003 b

C015/0025

Bear Cyn Mine 1/22/2003 5 Photos
NO3-46-2-2, 1 of 2
Exposed Outslope Reporting To Bear Creek
Note extensive acreage of untreated runoff.



01222003

C015/0025




Bear Cyn. #1 Mine Access Road
Obstructed Culvert C-27 @ Inlet
Hiawatha Intake Portal (2 pictures)
1/22/2003 10:10am


Obstructed Inlet @ Culvert C-17
Bear Cyn #1 Mine Storage Pad
N03-46-2-2, 2 of 2 C/015/025
1/22/2003 10:02am


Culvert C-27 - C/015/025
N03-46-2-2, 2 of 2 1/22/2003
Outlet end
1/22/2003 10:11am