

Pumping well drawdowns plotted in red
Spring discharges in the alluvial groundwater system plotted in blue
Monitoring well drawdowns in the clayey, silty alluvial groundwater plotted in green

Figure 18 Plots of water level responses and spring discharge rates during the pump-test at Y-61.