UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FROM OAKLEY

D1003[illegible]27

ROUTE TAKEN 10-17-40



10/17/90

~15:15 VIPONT MINE SITE D/003/007



10/17/90



CONCRETE PAD

- LEACHED MIL FAIRLY SOLID
- ASPHALT GUTTER @ W END OF HEAPS
- 3 VATS/TANKS EMPTY
- PONDS WERE LINED W/PLASTIC ONLY
- PLASTIC DRUM OF CAUSTIC SODA 50% LIQUID PURIFIED

VAN WATERS & ROGERS - HAD SEVERAL LABELS UNDERNEATH

- METAL DRUMS - CAUSTIC SODA 50% LIQUID
- FULL PLASTIC DRUM
- WATER DRAINING FROM PIPELINE NEAR TRAILER
- CYANOBRIK (SMALL BLACK DRUMS) FROM DuPONT
- FISH IN BIRCH CREEK BELOW BEAVER DAM BELOW VIPONT
- NO FISH SEEN IN STREAM NEAR OLD TAILINGS POND

~17:15 - LEFT SITE

adj FIELD NOTES

LOCATION OF WATER SAMPLING