
S/015/074
CLARK #1
THOMAS CLARK
S/015/046
ROBERT CLARK
S/015/053
BRET CLARK
S/015/043
BODY TODY
M/015/040
CO-OP PLACER
S/015/052
Miller Canyon
Christiansen Wash
Muddy Creek
Cowboy Mine
Flume
23
24
25
26
27
34
35
36
2
1
3

5/015/074
CLARK #1

92 EM 1
~~AMR/045/003~~ FROM FILE AMR/015/902
Cowboy Mine
Mesa Butte Quad

COWBOY CONSOL MINE



S/015/074
CLARK #1

92 EM 1
~~AMR/045/003~~ AMR/015/002
Cowboy Mine
Mesa Butte Quad

COWBOY CONSOL MINE

Adit #1: 15' high face-up area cut back 25' into west-facing slope. Sloughing of rock debris from above has closed opening to 1' h x 4' w. Before sloughing opening was approx. 5'-6' high. 12'-15' layered sandstone caprock.

Adit #2: Configuration similar to Adit #1. Opening 4' h x 10' w narrowing to 4' h x 9' w inside. Timber and steel sets. 4' massive sandstone caprock.

Adit #3: Configuration similar to Adit #1. Opening 4' h x 12' w; partial caving at 6'. Timber sets, 2" x 8" lumber caps. Porcelain insulator on one timber. 3'-4' massive sandstone caprock with another 10' of layered sandstone.

Adit #4: Opening 5' h x 12' w, closes to 3' h x 10' w about 10' inside. Timber sets, 2" x 8" lumber caps. Face-up is a vertical to overhanging cliff in the middle of a drainage gulley; sandstone and exfoliating carb shale.

Adit #1:



Adit #2:



Adit #3:



Adit #4:



PROJECT COMPLETED OCT. 1984

BY B&R RECLAMATION, ELMO UTAH

WILLIAM O'BRIEN