

file

September 5, 1978

0004

Memo to File:

Re: Valley Camp of Utah  
Utah No. 2 and Belina Mines  
ACT/007/014  
ACT/007/001

An inspection was made of the Utah No. 2 and the Belina Mines of Valley Camp of Utah on August 29, 1978 by Larry Demrau from O.S.M. and Mike Thompson from the Division.

The load-out facilities at the No. 2 Mine and the associated proposed sedimentation control facilities were shown to Mr. Damrau before a meeting with Mr. Trever Whiteside of Valley Camp was held.

The facilities at the Belina Mine were shown to Mr. Demrau. The unstable ground of this spring that resulted in slump failures along portions of the road and surface facility area has apparently stabilized. A sedimentation trap consisting of a small pond and gravel filter has been constructed on the uppermost surface facility area.

K. MICHAEL THOMPSON  
ENGINEERING GEOLOGIST

KMT/sp  
cc: O.S.M., Denver