

8/8/80

Route for
Comment A.S.A.P.

~~IS~~

Proceed. Per

pk

SWS

- 8-27-80

Letter went
out?
Lee

DWZ
9/24

No comment
MA
9-16

0026

VALLEY CAMP OF UTAH, INC.

Scofield Route
Helper, Utah 84526

A(1) 007/001

June 25, 1980


Mr. Ron Daniels
Division of Oil Gas & Mining
1588 West North Temple
Salt Lake City, Utah 84116

Dear Mr. Daniels

Please find enclosed, seven (7) more copies of our "Belina No. 1 Surface area & Slope Stabilization Plan."

I'm not sure who requested these additional copies, but apparantly the request was made to Mr. Haynes.

Sincerely,



Trevor G. Whiteside
Senior Mining Engineer

wc/cg

RECEIVED
JUN 25 1980

DIVISION OF
OIL, GAS & MINING

THE VALLEY CAMP COAL COMPANY

Scofield Route
Helper, Utah 84526

*Tom - Please
distribute w/
letter. R*

W. H. HAYNES, JR.
PRESIDENT, WESTERN DIVISION

GENERAL OFFICES
700 WESTGATE TOWER
CLEVELAND, OHIO 44116

April 29, 1980

Mr. Ron Daniels
Coordinator of Mined Land Development
Division of Oil, Gas, & Mining
1588 West North Temple
Salt Lake City, Utah 84116

RECEIVED
MAY 2 1980

Re: ACT/007/001

DIVISION OF
OIL, GAS & MINING

Dear Mr. Daniels,

Confirming our recent conversations in your offices, at the site of our Belina No. 1 Mine, permit No. ACT/007/001, we have experienced failure to the embankment cut below the mine portals above the area of permanent coal storage and reclaim facilities for the mine.

In order to stabilize this embankment, and also to achieve compliance with the surface mine regulatory program, it is necessary to construct a compacted fill embankment, with appropriate sub-drains to accommodate groundwater, against the cut face as indicated on the enclosed drawing dated March 17, 1980, seven copies of which were left with your office at the time of our meeting. With construction of this embankment, it is necessary to provide retained access to the Lower O'Connor seam by the placement of steel arch supported tunnel liners at the approximate elevation of the coal storage facility, as indicated on the drawing. This access, and tunnel liner installation will allow the eventual development of the Belina No. 2 Mine upon permit and mine plan approval. No development beyond installation of the tunnel liner is proposed at this time.

It is necessary to proceed with this work immediately so as not to jeopardize ongoing operations at Belina No. 1, which would occur with the failure of the embankment during the course of the present thawing and run-off conditions. We therefore request your approval of the plans as submitted as a minor modification of our approved permit and mine plan to achieve compliance with the permanent regulatory program, and to protect the viability and stability of our ongoing operation.

If we can provide additional information, please call on us.

Yours very truly,

W. H. Haynes, Jr.
W. H. Haynes, Jr.

whh:vy

Enclosure (7)

Document Information Form

Mine Number: C/007/0001

File Name: White Oak - Incoming

To: Ron Daniels - DOGM

From:

Person Trevor G. Whiteside

Company Valley Camp of Utah

Date Received: 6/25/04

Explanation: Belina No. 1 - Surface area & slope
stabilization plan. - Map.

cc: