

0030



United States Department of the Interior
OFFICE OF SURFACE MINING
Reclamation and Enforcement
BROOKS TOWERS
1020 15TH STREET
DENVER, COLORADO 80202

MSW
JWS

Route & file
ACT/007/014

Lee
8/6

TSS
RMK
5/4
DMM
9/8

July 2, 1980

Mr. Ron Daniels
Coordinator of Mined Land Development
Department of Natural Resources
1588 West North Temple
Salt Lake City, Utah 84116

gh

RECEIVED
JUL 07 1980

DIVISION OF
OIL, GAS & MINING

ACT/007/004

Dear Mr. Daniels:

Enclosed please find a copy(s) of on-site inspection report. The inspection was conducted within Utah #2 Mine of February 19, 1980, during the period

If you have any questions or problems, please contact this office.

Sincerely,

Thomas E. Ehmett, Acting Chief
Division of Inspection & Enforcement

REGION V ON-SITE INSPECTION REPORT

VALLEY CAMP OF UTAH, INC.
UTAH #2 MINE
Scofield Route
Helper, Utah 84526
(801) 488-9413


DATE: February 19, 1980
TIME: 3:30 p.m.
WEATHER: Clear, heavy snowcover
COUNTY & STATE: Carbon County, Utah
COMPANY OFFICIAL: Joe Shoemaker
STATE OFFICIAL: Joe Helfrich
OSM OFFICIAL: Larry Damrau
STATE PERMIT NO: ACT/007/014
MSHA I.D. NUMBER: 42-01185
NOV's: 80-5-18-7
STATE ENFORCEMENT
ACTIONS: None

GENERAL COMMENTS

A follow-up inspection was conducted to evaluate the remedial actions taken by the company to abate Notice of Violation #80-5-18-7 (Violation #1 of 1, Failure to maintain culvert which drains access road). Heavy snows had occurred the preceeding few days. It was evident that snow removal operations in the vicinity of the fan portal had been conducted in a manner to avoid blocking the culvert, as required in the remedial action.

The violation was terminated March 7, 1980, effective January 11, 1980, at which time the company had informed OSM that the required abatement actions had been conducted.

During the inspection, it was observed that the Utah #2 south sedimentation pond was being worked on. A decanter and emergency overflow had been installed and riprap was being placed at the discharge of the decanting 18 inch culvert.


LARRY DAMRAU
RECLAMATION SPECIALIST