

April 22, 1983

Inspection Memo  
to Coal File:RE: Valley Camp of Utah, Inc.  
Utah #2  
ACT/007/014  
Folder No. 7  
Carbon County, Utah

On April 12, 1983 DOGM Field Specialist Ken Wyatt conducted a partial inspection at the Utah #2 loadout. Steve Tanner of Valley Camp accompanied this inspector on the tour. The weather was overcast and cold with snow beginning during this inspection.

Drainages throughout the mine area appeared to be functional at this time. The inlet to sediment pond #2 is in continual need of maintenance to insure that disturbed area runoff does not flow out onto State road 96 and into Mud Creek. Little flow was observed draining into sediment pond #3 from the tipple/loadout area.

A slump has occurred on the downslopes of the disturbed area pad on the east side of sediment pond #1. The slumpage area was approximately 50 feet in length. This area should be examined on future inspections to determine the extent of any damage to the sediment pond or adjacent off-site areas. No compliance problems were observed at this time.

KEN WYATT *KW*  
FIELD SPECIALIST

KW/lm

cc: Tom Ehmett, OSM  
Trevor Whiteside, Valley Camp  
Joe Helfrich, DOGM

## Statistics:

Per Diem: 1 person X 1 day, 7.5 hours = \$50.78  
Vehicle: EX #45421 - 486 miles  
Grant: A & E