

January 18, 1984

Inspection Memo  
to Coal File:

RE: Valley Camp of Utah Inc.  
Belina Mine Complex  
ACT/007/001, Folder No 7  
Carbon County, Utah

On January 12, 1984, Division of Oil, Gas and Mining Field Specialist, Ken Wyatt, conducted a partial inspection of the Valley Camp facilities. Mr. Steve Tanner of Valley Camp accompanied this inspector. The weather was clear and cold with little snow melt occurring.

The mine water filter pond was functioning at the time of this inspection. The quality of the effluent appeared adequate. A sample of the mine water pond effluent was obtained by digging down through the snow in the vicinity of the parshall flume. This sample was collected at 4:00 p. m.

Sediment Pond No. 4 was also discharging at the time of this inspection. A sample of the discharge water was obtained at 3:45 p.m. by walking out on the pier to the overflow stand pipe. The sample was collected of the water dropping into this stand pipe. The quality of this water appeared to be in compliance.

Snow removal activity in the area of the material storage pad was observed. A dump truck was being loaded with snow from the pad and was hauling it down and dumping it off of the northern end of the truck turnaround pad above the sediment pond. All of this snow material will melt and flow into the sediment pond.

No runoff was occurring at this time, all ditches and berms appeared to be adequately maintained.

Ken Wyatt   
Field Specialist

KW:re  
cc: Tom Ehmett, OSM  
Trevor Whiteside, Valley Camp of Utah Inc.  
Joe Helfrich, DOGM  
Mary Boucek, DOGM

Statistics: See Co-op Mining Company, Trail Canyon Mine memo dated January 18, 1984