

John [unclear]



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Partial: _____ Complete: XX Exploration _____

Inspection Date/Time: January 28, 1993/08:00am-02:00pm

Date of Last Inspection: December 23, 1992

Mine Name: Belina Complex County: Carbon Permit Number: ACT/007/001
Permittee and/or Operator's Name: Valley Camp of Utah
Business Address: Scofield Route, Helper, UT 84526
Type of Mining Activity: Underground XX Surface _____ Prep. Plant _____ Other _____
Officials(s): State: Stephen J. Demczak Company: Ed Foust
Federal Official(s): _____ Weather Conditions: _____
Existing Acreage: Permitted-3136 Disturbed-79 Regraded- _____ Seeded- _____ Bonded-79
Increased/Decreased: Permitted- _____ Disturbed- _____ Regraded- _____ Seeded- _____ Bonded- _____
Status: Exploration/ X Active/ Inactive/ _____ Temp Cessation/ _____ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ _____ Liability _____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[]	[XX]	[]
2. SIGNS AND MARKERS	[XX]	[]	[]	[]
3. TOPSOIL	[XX]	[]	[]	[]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[]	[XX]	[]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[]	[XX]	[]
c. OTHER SEDIMENT CONTROL MEASURES	[XX]	[]	[]	[]
d. WATER MONITORING	[XX]	[]	[]	[]
e. EFFLUENT LIMITATIONS	[XX]	[]	[]	[]
5. EXPLOSIVES	[XX]	[]	[]	[]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]	[]	[]	[]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	[]	[]	[]
8. NONCOAL WASTE	[XX]	[]	[]	[]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[XX]	[]	[]	[]
10. SLIDES AND OTHER DAMAGE	[XX]	[]	[]	[]
11. CONTEMPORANEOUS RECLAMATION	[XX]	[]	[]	[]
12. BACKFILLING AND GRADING	[XX]	[]	[]	[]
13. REVEGETATION	[XX]	[]	[]	[]
14. SUBSIDENCE CONTROL	[XX]	[]	[]	[]
15. CESSATION OF OPERATIONS	[XX]	[]	[]	[]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	[]	[]	[]
b. DRAINAGE CONTROLS	[XX]	[]	[]	[]
17. OTHER TRANSPORTATION FACILITIES	[XX]	[]	[]	[]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	[]	[]	[]
19. AVS CHECK (4th Quarter-April, May, June)	[XX]	[]	[XX]	[]
20. AIR QUALITY PERMIT	[XX]	[]	[]	[]
21. BONDING & INSURANCE	[XX]	[]	[XX]	[]

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001 DATE OF INSPECTION: January 28, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

- a. The permit expires on August 24, 1994. The current permit was viewed and was signed by both parties.
- b. The new UNPDES permit was signed August 19, 1992. There was no discharge for fourth quarter.
- c. Sediment pond was inspected on October 26, 1992. The operator had not seen any problems. Ponds have been surveyed for sediment volume.
- d. Water monitoring samples were taken on August 31, 1992. Seven surface and eight ground water sites were taken. A new site was added S36-7 located at Upper Boardinghouse Canyon. No new sample was required for the rest of the year due to schedule in MRP.
- e. Valley Camp is insured by Home Indemnity and the policy has exceeded the required minimum coverage limits. The policy number is 6LR989061 and it expires on April 4, 1993.
- f. Reclamation agreement is by Home Indemnity Co. Policy Number 8099-56-50 with a bond set at 2.3 million dollars.

4a. Diversions -

The diversions were inspected and were functioning properly as snow covered several of the diversions. Not all diversions could be reached due to the snow cover.

4b. Sediment Ponds and Impoundments -

Sediment ponds were not discharging at the time of inspection. Snow, approximately 42 inches, covered the ponds, therefore, inspection was limited.

14. Subsidence Control -

The subsidence survey was taken on August 25-26, 1992 for Valley Camp and will be submitted in the annual report.

19. AVS Check -

An AVS Check has been taken at the mine site with no new changes in ownership and control.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Valley Camp of Utah, Ed Foust


Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: February 3, 1993

Inspector's Signature and Number:


Stephen J. Demozak

#39