

From: Priscilla Burton
To: Darin Caine; OGMCOAL
CC: Haddock, Daron; Owen, James
Date: 6/22/2011 12:45 PM
Subject: Re: 0070001 Outgoing White Oak mine site reclamation

Hi Darin,

Thank you. It is cleared. James Owen and I were just up there this morning. The site is greening up and the terraces have controlled the water flow. However, a good deal of water bypassed the lower terrace and flowed down the access road, then over the slope, creating quite a gully. We would like to avoid this situation by removing the dirt access road to the lower terrace. Would you like to meet at the site to discuss the change? The new channel is stable and passed water through drops and pools as designed. I will ask the contractor to return to the site in the next couple of weeks to finish up the work on the slopes and in the upper channel.

Priscilla Burton, CPSSc
Division Oil Gas & Mining
319 Carbonville Rd., Ste. C
Price UT 84501
(435) 613-3733

>>> Darin Caine <omanranches@hotmail.com> Wednesday, June 22, 2011 10:57 AM >>>
Ms. Burton, my logger says the whiskey creek road is clear. Darin

Sent from my iPhone

On Jun 20, 2011, at 11:46 AM, "Priscilla Burton" <priscillaburton@utah.gov>
> wrote:

> Thank you Darin.

>

>>>> Darin Caine <omanranches@hotmail.com> Monday, June 20, 2011 11:29

>>>> AM >>>>

> Ms. Burton, yes I will notify the logger that he needs to clear things

> out of the way. Thanks, Darin Caine

>

>

>

>

>