

**OGMCOAL - 0070001 White Oak mine access**

---

**From:** Priscilla Burton  
**To:** Caine, Darin; OGMCOAL  
**Date:** 9/17/2012 10:26 AM  
**Subject:** 0070001 White Oak mine access  
**CC:** Haddock, Daron

---

Hello Mr Caine,

I am required to inspect the abandoned, reclaimed White Oak mine site to ensure stability and sediment control. This inspection requirement is described in the Utah Coal Mining Rule R645-400-132.

I went to the site last Friday (September 14) and found that the Division lock had been removed and a new chain and lock now blocks access. I'd like to meet you or your logging contractor at the locked gate, so that I can place the Division's lock on the new chain, so that the Division has vehicle access again. Could you meet me there sometime during the next three weeks?

Given vehicle access, the Division of Oil, Gas & Mining will do a little re-seeding and thistle control at the site this fall.

Best Regards,

*Priscilla Burton*

Priscilla Burton, CPSSc  
Sr. Environmental Scientist  
Utah Division of Oil Gas & Mining  
319 No. Carbonville Rd, Ste.210  
Price UT 84501  
(435) 613-3733