



OGMCOAL DNR <ogmcoal@utah.gov>

Eccles pad and culvert

1 message

Priscilla Burton <priscillaburton@utah.gov>

Tue, Nov 3, 2015 at 2:51 PM

To: "cherylparker@utah.gov" <cherylparker@utah.gov>, Justin Hart - Utah Wildlife Resource <justinhart@utah.gov>, Daron Haddock <daronhaddock@utah.gov>, OGMCOAL DNR <ogmcoal@utah.gov>, Dana Dean <danadean@utah.gov>

Cc: Keenan Storrar <kstorrar@utah.gov>

FYI. These photos were taken today. They are laying back the slope to create a small floodplain. Bottom width is 10 feet. Floodplain width is 28 ft. Keenen was at the site this morning to help direct the work. Work will continue this week. Hope the weather holds.

Priscilla Burton, MS, CPSSc
Environmental Scientist III
Utah Division of Oil, Gas & Mining
Price Field Office
phone: [435-613-3733](tel:435-613-3733)

3 attachments



DSCN4453 laying back the slope.JPG
7099K



DSCN4468 culvert inlet silt fence water level roughed in channel.JPG
7096K



DSCN4470 beginning rock placement.JPG
7281K