

0013

SCOTT M. MATHESON
Governor

TEMPLE A. REYNOLDS
Executive Director,
NATURAL RESOURCES

CLEON B. FEIGHT
Director



STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS, AND MINING
1588 West North Temple
Salt Lake City, Utah 84116
(801) 533-5771

OIL, GAS, AND MINING BOARD

CHARLES R. HENDERSON
Chairman

JOHN L. BELL
EDWARD T. BECK
E. STEELE McINTYRE
BOB NORMAN
MARGARET BIRD
HERM OLSEN

November 6, 1981

Ms. Shirley Lindsay
Office of Surface Mining
Brooks Towers
1020 15th Street
Denver, Colorado 80202


RE: Price River Coal Company
Crandall Canyon Mine Modification
ACT/007/004
Carbon County, Utah

Dear Shirley:

Not being able to reach you all week, we have decided to wait until Monday, November 9, 1981, for your response to the road modification to the modification to the mine plan. Enclosed is our, completed Determination of Completeness response to Price River Coal Company's response to the Apparent Completeness Review. As you may see it is nearly complete and areas concerning the road have been addressed. If you have already completed your review of the road modification to the modification to the mine plan and noted otherwise please call me.

Price River Coal Company has been very responsive to our requests for information and we see no reason why their initiation of road construction should be held up any further. I will be awaiting your response this Monday, thank you.

Sincerely,



THOMAS N. TETTING
ENGINEERING GEOLOGIST

TNT/te