

0003

ACT/007/004 #3

PRICE RIVER COAL COMPANY

P.O. BOX 629 HELPER, UTAH 84526 (801) 472-3411

November 2, 1983

CERTIFIED RECEIPT REQUESTED
Certified No. P290 262 248

Mr. Dave Darby, Staff Hydrologist
Division of Oil, Gas, and Mining
4241 State Office Building
Salt Lake City, Utah 84114

Re: Subdrainage System to be Installed in the Upper Crandall Site

Dear Mr. Darby:


Please find enclosed a copy of the construction drawing for installation of the subdrainage system to be installed in the upper Crandall Canyon site. Designed to relieve lateral pressure caused by water buildup behind the retaining wall, K. Hutchinson and I discussed this matter with you in your office on 10-19-83. Proceeding on your verbal approval we have requested bids on the necessary work including repair of failed sections of the retaining wall and subdrain installation. We hope to commence the work by 11-14-83.

You suggested that we closely monitor the effluent from the subdrain, after installation, to determine possible problems in water quality. We do not expect problems but will continue to monitor as requested.

Should you need any additional information, please contact me.

Very truly yours,

PRICE RIVER COAL COMPANY


Rob L. Wiley
Environmental Engineer

RLW:jp

Enclosure

cc: K. Hutchinson

RECEIVED
NOV 7 1983

DIVISION OF
OIL, GAS & MINING

