

Document Information Form

Mine Number: C/007/004

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A.

Date Sent: APRIL 20, 1983

Explanation:

INSPECTION MEMO TO COAL FILE.

cc:

File in: C/007, 004, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

April 20, 1983

Inspection Memo
to Coal File:

RE: Price River Coal Company
Price River Coal Complex
ACT/007/004
Folder No. 7
Carbon County, Utah

On March 2, 1983 a partial inspection was conducted at the above mentioned minesite by Division Inspector David Lof. He was accompanied on the inspection by Rob Wiley of Price River Coal Company (PRCC).

Sowbelly Canyon

During the February complete inspection the operator was asked to maintain sediment control structures along the mine access road near the guardhouse. Since that time he has maintained the water bar across the access road just below the guard shack. They also reestablished the diversion to sediment pond 005 and had installed straw bales along the west side of the mine access road.

Hardscrabble Canyon

The inlets to all of the sediment ponds had been maintained in order to insure runoff would be conveyed to its designated sediment pond. There has been a considerable amount of materials sloughed off of the cut slopes into the undisturbed diversions in both Sowbelly and Hardscrabble Canyons. The operator will need to clean out the undisturbed diversions this spring.

Crandall Canyon

Cementation had removed all of their equipment from the minesite except for one trailer down by the #2 Shaft. The trailer was supposed to be removed this week. The operator committed to establishing a new disturbed area runoff diversion to the sediment pond by the #2 Shaft as soon as the last trailer is out and weather permitting. The collar on the #2 Shaft had been completed.

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No. 0010 Date 4-20-83


In C/007, 004, Internal

For additional information _____

INSPECTION MEMO TO COAL FILE
ACT/007/004
April 20, 1983
Page 2

Castlegate Preparation Plant

The operator has halted the practice of pushing snow removal waste from the refuse pile access road onto the downslope of the previously undisturbed hillside above and to the east of the raw coal stacking tube.



DAVID LOF
FIELD SPECISLIST

DL/lm

cc: Tom Ehmett, OSM
Joe Helfrich, DOGM
Bart Kale, DOGM
Rob Wiley, PRCC

Statistics:

See Deer Creek mine memo dated March 15, 1983.