

0005

PRICE RIVER COAL COMPANY
P.O. BOX 629 HELPER, UTAH 84526 (801) 472-3411

*File ACT/007/004, Folder
#2, 3, 4*



RECEIVED

NOV 14 1985

**DIVISION OF OIL
GAS & MINING**

HAND DELIVERED

November 14, 1985

Dr. Dianne R. Nielson, Director
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

Re: Special Conditions for Permit No. UT-0007

Dear Dr. Nielson:

Pursuant to Mr. L.P. Braxton's letter of November 6, 1985, the proposed modifications to the drainage control plan for our facilities in Hardscrabble Canyon have been reevaluated using an SCS Type II rainfall distribution. Since the hydraulic designs in the original permit were based upon the 10-year, 24-hour storm event, the reevaluation was conducted using this same frequency storm.

The attached revisions are intended to replace our submittal of October 31, 1985. The only items from the original submittal that must be incorporated into the revisions are Table 7-13(A) and Exhibit 3.3-12. The remainder of the text, figures, tables and exhibits have been revised and should be replaced with the corresponding attached item.

If there are any questions regarding the submittal, please contact me at (801) 472-3411. Your prompt attention to this matter is appreciated.

Sincerely,

PRICE RIVER COAL COMPANY

Kenneth B. Hutchinson
Chief Engineer

KBH:jb

Attachments