



NO. N B6-4-13-2

notice of violation

To the following Permittee or Operator:

Name CASTLE GATE COAL COMPANY

Mine PRICE Surface Underground Other

County CARBON State UTAH Telephone _____

Mailing Address P.O. Box 449 HELPER, UT 84526

State Permit No. ACT/007/004

Ownership Category State Federal Fee Mixed

Date of inspection SEPT. 26, 19 86

Time of inspection 7:30 a.m. p.m. to 12:15 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing SEPT. 30, 1986 Time of service/ mailing 4:20 a.m. p.m.

RICHARD H. ALLISON, JR.
Permittee/Operator representative

PROJECT SUPERVISOR
Title

ISSUED FROM THE DIVISION OFFICE
Signature

MINING FIELD SPECIALIST
Title

#4
Identification Number

DAVID LOF
Division of Oil, Gas & Mining representative
David Lof
Signature

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N86-4-13-2

Violation No. 1 of 2

Nature of violation

FAILURE TO CONDUCT SURFACE COAL MINING ACTIVITIES IN ACCORDANCE WITH AN APPROVED PERMIT

FAILURE TO MAINTAIN SEDIMENT CONTROLS

Provisions of act, regulations or permit violated

UMC 771.19

UMC 817.45

Portion of operation to which notice applies

CASTLE GATE PREP PLANT DIVERSION D-4, CULVERT C-4 AND THE REFUSE HAUL ROAD

Remedial action required (including any interim steps)

- 1) RECONSTRUCT D-4 TO MEET DESIGN SPECIFICATIONS
- 2) MAINTAIN THE INLET OF C-4
- 3) REGRADE THE REFUSE HAUL ROAD TO PROVIDE PROPER ROAD DRAINAGE AND ENSURE THAT ALL ROAD RUNOFF IS DIVERTED TO THE APPROPRIATE SEDIMENT CONTROL STRUCTURES

Abatement time (including interim steps)

OCTOBER 10, 1986



NOTICE OF VIOLATION NO. N86-4-13-2

Violation No. 2 of 2

Nature of violation

FAILURE TO MAINTAIN SEDIMENT PONDS TO PREVENT SHORT CIRCUITING TO THE EXTENT POSSIBLE

Provisions of act, regulations or permit violated

UMC 817.46 (c)

Portion of operation to which notice applies

SEDIMENT PONDS OIL AND OIL-B

Remedial action required (including any interim steps)

REPAIR LEAKS IN THE POND'S SPILLWAY SYSTEM TO PREVENT SHORT CIRCUITING AND ENSURE THAT EFFLUENT LIMITATIONS ARE MET.

Abatement time (including interim steps)

OCTOBER 10, 1986