

0046

*Name File, S. Linnell*

*Act/007/009*



**CASTLE  
GATE**  
COAL COMPANY

RECEIVED  
JAN 14 1987

January 12, 1987

DIVISION OF  
OIL, GAS & MINING

Mr. Lowell Braxton, Administrator  
Division of Oil, Gas & Mining  
Three Triad Center, Suite 350  
Salt Lake City, UT 84180-1203

Dear Mr. Braxton:

During our last regular inspection, Mr. David Lof noticed that the western permit boundary at Castle Gate Preparation Plant did not follow exactly the disturbed area shown on Map No. 3.4-1. Therefore, I would like to know if an Insignificant Boundary Revision of this area is necessary.

*} Sure: can we discuss that, please. hmb  
1-15*

The area in question is triangular in shape, approximately 50 tapering to 10 feet for a length of 250 feet or about .2 acres ±. This area was previously disturbed prior to 1977.

Castle Gate Coal Company did not make this disturbance outside the permit boundary. This was done by Price River Coal Company prior to Castle Gate Coal Company acquisition.

If you require any further information, please call me at our Portal No. 3 office (801/472-8661).

Sincerely,

*Richard H. Allison, Jr.*  
Richard H. Allison, Jr., P.E.  
Project Supervisor

RHA:sk

cc: David Miller  
DOGM File  
Chrono

RHA/024