

0003



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

February 8, 2001

TO: Internal File
THRU: Daron R. Haddock, Permit Supervisor
FROM: Joseph C. Helfrich, Senior Reclamation Specialist
RE: 2000 Third Quarter Water Monitoring, Castle Gate Holding Company, Castle Gate Mine, C/007/004-WQ00-3

1. Was data submitted for all of the MRP required sites? YES [] NO [X]
Identify sites not monitored and reason why, if known:
field data missing for pond 020

2. On what date does the MRP require a five-year resampling of baseline water data.
See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.

Resampling due: Permit expires 12/24/2004

3. Were all required parameters reported for each site? YES [X] NO []
Comments, including identity of monitoring site:

4. Were irregularities found in the data? YES [] NO [X]
Comments, including identity of monitoring site:

5. Were DMR forms submitted for all required sites?
1st month, YES [X] NO []
2nd month, YES [X] NO []
3rd month, YES [X] NO []
Identify sites and months not monitored:

6. **Were all required DMR parameters reported?** YES NO
Comments, including identity of monitoring site:

7. **Were irregularities found in the DMR data?** YES NO
Comments, including identity of monitoring site:

8. **Based on your review, what further actions, if any, do you recommend?**

Provide consistent field data that is not combined with the field data for the willow creek mine.