

0001

007/005 # 5

December 15, 1987

TO: Coal File

FROM: Holland Shepherd, Reclamation Specialist *HHS*

RE: Spanish Fork Coalyard, Skyline Mine, ACT/007/005, Folder No. 5, Carbon County, Utah

I conducted an inspection of the Searle Trucking Company coalyard in Spanish Fork on December 7, 1987, at 3:00 p.m. No sign of any type of processing activity was evident. The screening device (referred to in my memo to the Coal File, dated December 3, 1987) had been removed.

During a telephone conversation with Bill Shriver of Utah Fuel Company, I was informed that the screening machinery had been taken to the Skyline Mine site. An inspection at Skyline on December 7, 1987, at 5:30 p.m., verified that the equipment was operational at the mine site.

jr
cc: K May
L. Braxton
S. Linner
1374R/3