



0073

*Priscilla
C/007/005
Copy Priscilla
done*

Date: 11-20-02

FAX COVER SHEET

To: Priscilla Buxton

Company: DGM

Fax No: (801) 359-3940

From: Skyline Mines
HC 35 Box 380
Helper, UT 84526
Fax Number: (435) 448-2632
Direct Dial: (435) 448-2669

Pages: 13 (including this one)

Notes: Pre-subsidence survey to USFS, Proce.
River Water Users, & Proce. River Water
Improvement District

Confidentiality Notice: This message is intended only for the use the individual or entity designated above, is confidential, and may contain information that is legally privileged or exempt from disclosure under applicable law. You are hereby notified that any dissemination, distribution, copying, or use of or reliance upon the information contained in and transmitted with this facsimile transmission by or to anyone other than the recipient designated above by the sender is *not authorized and strictly prohibited*. If you have received this communication in error, please immediately notify the sender by telephone and return it to the sender by U.S. Mail, or destroy it if authorization is granted by the sender.

If you have any trouble receiving the above specified pages, please call sender.



Canyon Fuel Company, LLC
Skyline Mines
HC 35 Box 380
Helper, Utah 84526
(435) 448-6463 Fax: (435) 448-2632

Via Certified Mail

November 20, 2002

Ms. Elaine Zieroth
Forest Supervisor
Manti-LaSal National Forest
599 West Price River Drive
Price, UT 84501

RE: Pre-Subsidence Survey of the North Lease (Winter Quarters) Tract, Skyline Mine, Canyon Fuel Company, LLC

Dear Ms. Zieroth:


As required by State Regulations R645-301-525.110 and 525.120, Canyon Fuel Company, LLC Skyline Mine has conducted a pre-subsidence survey of the area known to the mine as the North Lease area or the Winter Quarters Lease area. The location of the North Lease area is illustrated on the attached map. Skyline Mine intends to begin development mining in this area in December 2002 and longwall mining in the second quarter of 2004. Subsidence will not occur in this area until longwall mining commences.

As part of the survey, the locations of all surface structures such as buildings, roads, communication towers, and pipelines within the area to be subsided are determined and illustrated on a map.

The pre-subsidence survey was conducted in the fall of 2002 of the North Lease area (Winter Quarters Lease). A map was generated to illustrate the locations of any structures, water rights, and renewable resource lands that could be adversely affected by subsidence. This map is included with this letter and illustrates the projected locations of mining, the locations where surface cracks may appear as a result of subsidence, and surface and ground water right locations. No buildings, pipelines, or maintained roads were found in the areas to be subsided as a result of implementing the current North Lease mine plan. A poorly maintained pack trail does cross the area in the bottom of Winter Quarters Canyon and north of Bob's Canyon. No subsidence related impact is anticipated on the trail. The mine currently has approval to do development mining in the North Lease area from the Manti-LaSal National Forest Service (pending mining permit approval) and will not subside any of the perennial streams without approval from the Forest and the Division of Oil, Gas and Mining. The Forest has indicated to Skyline Mine the forest land is considered to have renewable resources related to wildlife and grazing. The timber resources are extremely limited and isolated in this area of the Forest and likely will not be harvested (Carter Reed, Manti-La Sal National Forest, Oral Communication 10-2002).

If you have any questions regarding this letter or would like to discuss future mining plans for the above referenced area. please call Mark Bunnell at (435) 448-2633 or me at (435) 448-2609.

Sincerely,



Doug Johnson
Technical Services Manager, Skyline Mine
Canyon Fuel Company, LLC.

xc: Pamela Grubaugh-Littig, Utah Division of Oil, Gas & Mining

enclosure

0.004

3570 8333

U.S. Postal Service
CERTIFIED MAIL RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

OFFICIAL USE

Postage	\$	Postmark Here
Cancelled Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement Required)		
Total Postage & Fees	\$	


Sent To

Street, Apt. No.,
or PO Box No.

City, State, ZIP+4

PS Form 3800, April 2002

See Reverse for instructions



SKYLINE MINE

11/20/02 16:37 FAX 435 448 2632



Canyon Fuel Company, LLC

Skyline Mines

HC 35 Box 380

Helper, Utah 84526

435/448-6463 Fax: 435/448-2632

TO:

Ms. Elaine Zieroth

Forest Supervisor

Manti-La Sal National Forest

599 West Price River Drive

Price, UT 84501

Is your RETURN ADDRESS completed on the reverse side?

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, 4a, and 4b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

- 1. Addressee's Address
- 2. Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:

Ms. ELAINE Eieroth
 Forest Supervisor
 Manti-La SAL National Forest
 599 West Price River Drive
 Price, UT 84501

4a. Article Number

7002 0860 0005 3570 0311

4b. Service Type

- Registered Certified
- Express Mail Insured
- Return Receipt for Merchandise COD

7. Date of Delivery

5. Received By: (Print Name)

6. Signature: (Addressee or Agent)

X

8. Addressee's Address (Only if requested and fee is paid)

PS Form 3811, December 1994

Domestic Return Receipt

Thank you for using Return Receipt Service.



Canyon Fuel Company, LLC
Skyline Mines
HC 35 Box 380
Helper, Utah 84526
(435) 448-6463 Fax: (435) 448-2632

Via Certified Mail

November 20, 2002

Price River Water Users Association
90 North 100 East
Price, Utah 84501

RE: Pre-Subsidence Survey of the North Lease (Winter Quarters) Tract, Skyline Mine, Canyon Fuel Company, LLC

Dear Sirs:


As required by State Regulations R645-301-525.110 and 525.120, Canyon Fuel Company, LLC Skyline Mine has conducted a pre-subsidence survey of the area known to the mine as the North Lease area or the Winter Quarters Lease area. The location of the North Lease area is illustrated on the attached map. Skyline Mine intends to begin development mining in this area in December 2002 and longwall mining in the second quarter of 2004. Subsidence will not occur in this area until longwall mining commences.

As part of the survey, the locations of all surface structures such as buildings, roads, communication towers, and pipelines within the area to be subsided are determined and illustrated on a map.

The pre-subsidence survey was conducted in the fall of 2002 of the North Lease area (Winter Quarters Lease). A map was generated to illustrate the locations of any structures, water rights, and renewable resource lands that could be adversely affected by subsidence. This map is included with this letter and illustrates the projected locations of mining, the locations where surface cracks may appear as a result of subsidence, and surface and ground water right locations. No buildings, pipelines, or maintained roads were found in the areas to be subsided as a result of implementing the current North Lease mine plan. A poorly maintained pack trail does cross the area in the bottom of Winter Quarters Canyon and north of Bob's Canyon. No subsidence related impact is anticipated on the trail. The mine currently has approval to do development mining in the North Lease area from the Manti-LaSal National Forest Service (pending mining permit approval) and will not subside any of the perennial streams without approval from the Forest and the Division of Oil, Gas and Mining. The Forest has indicated to Skyline Mine the forest land is considered to have renewable resources related to wildlife and grazing. The timber resources are extremely limited and isolated in this area of the Forest and likely will not be harvested (Carter Reed, Manti-La Sal National Forest, Oral Communication 10-2002).

If you have any questions regarding this letter or would like to discuss future mining plans for the above referenced area, please call Mark Bunnell at (435) 448-2633 or me at (435) 448-2609.

Sincerely,



Doug Johnson
Technical Services Manager, Skyline Mine
Canyon Fuel Company, LLC.

xc: Pamela Grubaugh-Littig, Utah Division of Oil, Gas & Mining

enclosure

U.S. Postal Service
CERTIFIED MAIL RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

OFFICIAL USE

Postage	
Qualified Fee	
Return Receipt Fee (Endorsement Required)	
Restricted Delivery Fee (Endorsement Required)	
Total Postage & Fees	\$

Send To

Street, Apt. No.,
or PO Box No.

City, State, ZIP+4

PS Form 3800 Apr 2002 See Reverse for Instructions



Canyon Fuel Company, LLC
Skyline Mines
HC 35 Box 380
Helper, Utah 84526
435/448-6463 Fax: 435/448-2632

TO:

Price River Water Users Assoc.
90 North 100 East
Price, UT 84501

008 3570 8328 0005 0860 7002

SKYLINE MINE

11/20/02 16:37 FAX 435 448 2632

009

SKYLINE MINE

11/20/02 16:38 FAX 435 448 2632

Is your RETURN ADDRESS completed on the reverse side?

SENDER: ■ Complete items 1 and/or 2 for additional services. ■ Complete items 3, 4a, and 4b. ■ Print your name and address on the reverse of this form so that we can return the card to you. ■ Attach this form to the front of the mailpiece, or on the back if space does not permit. ■ Write "Return Receipt Requested" on the mailpiece below the article number. ■ The Return Receipt will show to whom the article was delivered and the date delivered.		I also wish to receive the following services (for an extra fee): 1. <input type="checkbox"/> Addressee's Address 2. <input type="checkbox"/> Restricted Delivery Consult postmaster for fee.
3. Article Addressed to: Price River Water Users Assoc. 90 N. 100 E Price, UT 84501	4a. Article Number 9002096 20005.3570 8328	Thank you for using Return Receipt Service.
5. Received By: (Print Name) 6. Signature: (Addressee or Agent) X	4b. Service Type <input type="checkbox"/> Registered <input checked="" type="checkbox"/> Certified <input type="checkbox"/> Express Mail <input type="checkbox"/> Insured <input checked="" type="checkbox"/> Return Receipt for Merchandise <input type="checkbox"/> COD	
7. Date of Delivery 8. Addressee's Address (Only if requested and fee is paid)		

PS Form 3811, December 1994

Domestic Return Receipt



Canyon Fuel Company, LLC
Skyline Mines
HC 35 Box 380
Helper, Utah 84626
(435) 448-6463 Fax: (435) 448-2632

Via Certified Mail

November 20, 2002

Mr. Phillip P. Palmer
Price River Water Improvement District
P.O. Box 903
Price, Utah 84501

RE: Pre-Subsidence Survey of the North Lease (Winter Quarters) Tract, Skyline Mine, Canyon Fuel Company, LLC

Dear Mr. Palmer:


As required by State Regulations R645-301-525.110 and 525.120, Canyon Fuel Company, LLC Skyline Mine has conducted a pre-subsidence survey of the area known to the mine as the North Lease area or the Winter Quarters Lease area. The location of the North Lease area is illustrated on the attached map. Skyline Mine intends to begin development mining in this area in December 2002 and longwall mining in the second quarter of 2004. Subsidence will not occur in this area until longwall mining commences.

As part of the survey, the locations of all surface structures such as buildings, roads, communication towers, and pipelines within the area to be subsided are determined and illustrated on a map.

The pre-subsidence survey was conducted in the fall of 2002 of the North Lease area (Winter Quarters Lease). A map was generated to illustrate the locations of any structures, water rights, and renewable resource lands that could be adversely affected by subsidence. This map is included with this letter and illustrates the projected locations of mining, the locations where surface cracks may appear as a result of subsidence, and surface and ground water right locations. No buildings, pipelines, or maintained roads were found in the areas to be subsided as a result of implementing the current North Lease mine plan. A poorly maintained pack trail does cross the area in the bottom of Winter Quarters Canyon and north of Bob's Canyon. No subsidence related impact is anticipated on the trail. The mine currently has approval to do development mining in the North Lease area from the Manti-LaSal National Forest Service (pending mining permit approval) and will not subside any of the perennial streams without approval from the Forest and the Division of Oil, Gas and Mining. The Forest has indicated to Skyline Mine the forest land is considered to have renewable resources related to wildlife and grazing. The timber resources are extremely limited and isolated in this area of the Forest and likely will not be harvested (Carter Reed, Manti-La Sal National Forest. Oral Communication 10-2002).

If you have any questions regarding this letter or would like to discuss future mining plans for the above referenced area, please call Mark Bunnell at (435) 448-2633 or me at (435) 448-2609.

Sincerely,



Doug Johnson
Technical Services Manager, Skyline Mine
Canyon Fuel Company, LLC.

xc: Pamela Grubaugh-Littig, Utah Division of Oil, Gas & Mining

enclosure

012

SEE 05E 5000 0005 3570 8335

U.S. Postal Service
CERTIFIED MAIL RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

OFFICIAL USE

Postage	\$	Postmark Date
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement Required)		
Total Postage & Fees	\$	


Sent To

Street, Apt. No.,
or PO Box No.

City, State, ZIP+4

PS Form 3800, April 2002 See Reverse for Instructions

PLACE STICKER AT TOP OF ENVELOPE TO PROTECT FROM
CF THE RETURN ADDRESS FIELD AT BOTTOM OF ENVELOPE
CERTIFIED MAIL



7002 0860 0005 3570 8335

SKYLINE MINE

11/20/02 16:38 FAX 435 448 2632

 **Canyon Fuel Company, LLC**
 Skyline Mines
 HC 35 Box 380
 Helper, Utah 84526
 435/448-6463 Fax: 435/448-2632

TO:

Mr. Phillip P. Palmer
Price River Water Improvement Dist.
 P.O. Box 903
 Price, UT 84501

Is your RETURN ADDRESS completed on the reverse side?

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, 4a, and 4b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

- 1. Addressee's Address
- 2. Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:

Mr. Phillip P. Palmer
Price River Water Improvement Dist.
P.O. Box 903
Price, UT 84501

4a. Article Number

7002 0860 0005 3570 8335

4b. Service Type

- Registered Certified
- Express Mail Insured
- Return Receipt for Merchandise COD

7. Date of Delivery

5. Received By: (Print Name)

6. Signature: (Addressee or Agent)

X

8. Addressee's Address (Only if requested and fee is paid)

Thank you for using Return Receipt Service.