



# PLATEAU MINING COMPANY

A SUBSIDIARY OF UNITED NUCLEAR CORPORATION

Producers & Sellers of Utah Low Sulphur Coal

P.O. Drawer PMC

Price, Utah 84501

Phone 637-2875

July 17, 1978

CERTIFIED - RETURN RECEIPT REQUESTED

*3RD. REV.  
A map of this  
R.O.W is enclosed.*

Mr. Henry C. Wilson, Acting Chief  
Branch of Lands & Minerals Operations  
U.S. Dept. of Interior - B.L.M.  
University Club Building  
136 East South Temple  
Salt Lake City, UT 84111

Subject: U-39779; Access Road  
Right-of-Way

Dear Mr. Wilson:

Due to adverse construction problems we have been forced to revise the location of the road r.o.w. The location is approximately the same as the original location with the switchbacks moved farther west.

Changes in culvert locations are listed on the drawing under Note No. 2.

Please find enclosed one (1) sepia and five (5) blueprint copies of the revised location.



TFB:aj

Enclosures

Sincerely yours,

Thomas F. Bailey  
Executive Vice President &  
General Manager