

0047

UT 0018

**PLATEAU MINING COMPANY**

"a subsidiary of getty mineral resources company"

P.O. DRAWER PMC  
Price, Utah 84501  
Telephone: (801) 637-2875

July 29, 1980

Mr. Donald A. Crane  
Director, Region V  
Office of Surface Mining  
Brooks Towers  
1020 15th Street  
Denver CO 80202

Re: Hydrologic Monitoring and  
Runoff Control Plan

Dear Mr. Crane:


By way of this letter Plateau Mining Company requests a thirty (30) day extension for implementing its hydrologic monitoring and runoff control plan.

The three-month period given us for full implementation ends August 1 and construction is still in progress. It is felt that all construction will be completed within the next thirty-day period.

To date, Plateau has constructed six sedimentation ponds, put in place 2500 feet of five foot culvert, graded and put in berms along several miles of road and belt line. Down spouts and collection boxes are in place as required. The only area that is lacking for total compliance is the Lion Portal site. Construction on this part of the plan is now underway and expected to be completed in the near future. It should be noted that all runoff from this area currently passes through the sedimentation pond located below this deck. The diversions required to separate the disturbed area water and the non-disturbed area water still need to be installed.

We would appreciate your immediate attention in granting this request in this matter. Also, would you please look again at our request for extending entries in the Mud Water Lease, Federal Lease U-37045, beyond the limits set forth in your March 12, 1980 letter?

Sincerely,



Floyd J. Tucker  
Executive Vice President &  
General Manager

cc: Moffitt, USGS, SLC  
Christensen, USFS, Price  
Daniels, DOGM, SLC  
Wicks, BLM, SLC  
Emmett, OSM, Denver  
Rigby, PMC