

0031

**PLATEAU MINING COMPANY**

A Subsidiary of Getty Mineral Resources Company

P.O. Drawer PMC

Price, Utah 84501-0904

Telephone (801) 637-2875

FILE: ACT/007/006

DWH 10/2/81

September 21, 1981

Mr. Wayne Hedberg  
Division of Oil, Gas, and Mining  
1588 West North Temple  
Salt Lake City, Utah 84116

Ref: Phone Conversation 09/21/81  
#4 Sediment Pond & Access


Dear Wayne,

In order to clean the sediment from our #4 pond, it will be necessary to improve the road running around Clifford Smith's home. This road is on private land, and is Mr. Smith's principal access to the balance of his property; He has indicated that he has no real problems with this activity and may in fact appreciate the work being done.

In order not to delay the reconstruction of the #4 impounding structure Plateau Mining Company is proceeding with construction at this time. As I indicated in our conversation, this pond is being impacted with considerable sediment and I will appreciate your input as to what means may be available to alleviate this problem.

Sincerely ,

PLATEAU MINING COMPANY

  
Melvin Coonrod  
Environmental Coordinator

REGISTERED  
SEP 24 1981

DIVISION OF  
OIL, GAS & MINING

MC/jlf