

0016

PLATEAU MINING COMPANY

A Subsidiary of Getty Oil Company
P.O. Drawer PMC Price, Utah 84501
Telephone (801) 637-2875

File ACT/007/006
Folder u.2
MRP
B Wayne

JIM

RECEIVED
OCT 13 1983

OCT 14 1983

October 11, 1983

Mr. James Smith
Division of Oil, Gas & Mining
4241 State Office Building
Salt Lake City, Utah 84114

DIVISION OF
OIL, GAS & MINING

Re: Corner Canyon Fan

Dear Mr. Smith:

The approved plan for the fan installation calls for a diesel fuel tank to be located above ground. This installation would have required the tank to be insulated to prevent jelling of the fuel during winter months. There is no insulation available that will withstand effects of diesel fuel without disintegrating.

We would like to bury the tank as shown on the enclosed drawings, Exhibits 6 and 8. To comply with Mine Safety and Health Administration regulations, the tank must be 100 feet from the portal.


The tank is a special corrosion resistant tank with a twenty year warranty. It will have a fuel level indicator with a sending unit which will give the fuel level to our warehouse. This will allow us to monitor the tank for leaks. Any leak will promptly be repaired.

This installation will be environmentally as sound as the approved plan.

We are assuming this is a minor change to the approved plan and will await your expeditious review.

Respectfully,

PLATEAU MINING COMPANY



Ben A. Grimes

BAG:sd

Enclosures

cc: Walt Novak - U.S.F.S. Manti-LaSal, Price