

0040

# PLATEAU MINING COMPANY

A Subsidiary of Getty Mining Company

P.O. Drawer PMC

Price, Utah 84501

Telephone (801) 637-2875

July 18, 1983

ACT/007/006  
#3

Mr. Wayne Hedberg  
D.O.G.M.  
4241 State Office Bldg.  
Salt Lake City, Utah 84111

RE: SEDIMENT POND MODIFICATION PLAN

Dear Wayne,


We would like to thank you for the two-week extension to submit the modification plan for sediment ponds 4, 5, and 6. As I told you on the phone today, we were delayed because of late receipt of water analysis from Ford Chemical Laboratory.

A majority of the modification plan has been completed but we needed a particle size distribution analysis to calculate settlement times.

We will have the plan submitted by July 29, 1983. If you have any questions, please phone.

Sincerely,

PLATEAU MINING COMPANY



Ben Grimes  
Environmental Coordinator


BG/lm

cc: B. Lauman


RECEIVED  
JUL 26 1983

DIVISION OF  
OIL, GAS & MINING


SECTION A-A  
N.T.S.



SECTION B-B  
NTS.



SECTION C-C  
N.T.S.



NOTE: THE APPROVED DITCH DESIGN CALLS FOR 1:1 SIDE SLOPES, 3.7' DEPTH, 2' BOTTOM WIDTH AND 13.07 FT<sup>2</sup> FLOW AREA.  
IN AREAS WHERE HORIZONTAL AREA LIMITATIONS EXIST, THE DITCH SHAPE MAY BE VARIED - 13.07 FT<sup>2</sup> FLOW AREA SHALL BE MAINTAINED.