



4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

October 12, 1983

P 396-996-828
CERTIFIED RETURN RECEIPT REQUESTED

Mr. Ben Grimes
Environmental Coordinator
Plateau Mining Company
P. O. Drawer EMC
Price, Utah 84501

RE: Plans submitted July 18, 1983
for abatement of NOV N83-4-5-1
Star Point Mines
ACT/007/006, Folder No. 3 & 7
Carbon County, Utah

Dear Mr. Grimes:

While reviewing the above mentioned submittal I found a number of discrepancies between the maps submitted and Plate 7-8 entitled "Surface Runoff Facilities and Sedimentation Control Plan for the Plateau Mine," of your approved permit application. These discrepancies must be addressed before the Division can continue the review of this submittal.

The first six items are a result of a comparison between Map 4, No. 1 of 2 entitled "Plateau Unit Train Loadout Surface Water and Sedimentation Control Facilities Map" and Plate 7-8 of the approved permit application. The last four are the result of a comparison between Map 4, No. 2 of 2 and Plate 7-8.

1. There appears to be a difference in the size of the area contributing runoff to Sediment Pond No. 2. In addition there is no discussion of the fourteen inch culverts, located along the conveyor to the coal stockpile, which contribute runoff to Sediment Pond No. 2 from the mine access road and road accessing the rock tunnel area.
2. Why isn't the proposed twelve inch culvert, shown on Plate 7-8 just north of the Starpoint No. 1 mine, along the road which connects the No. 1 and No. 2 mines, shown on Map 4, 1 of 2?
3. The existing fifteen inch Downspout No. 6 and its associated one foot berm are shown on Plate 7-8, why are they not shown on Map 4, 1 of 2?

FILE ACT/007/006
FOLDER #7



SCOTT M. MATHESON
Governor

OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON
Executive Director,
NATURAL RESOURCES

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS, AND MINING
1588 West North Temple
Salt Lake City, Utah 84116
(801) 533-5771

CHARLES R. HENDERSON
Chairman

CLEON B. FEIGHT
Director

JOHN L. BELL
C. RAY JUVELIN
THADIS W. BOX
MAXILIAN A. FARBMAN
EDWARD T. BECK
E. STEELE McINTYRE

Vacation or Termination of Notice or Order

To the Following Permittee or Operator:

Name PLATEAU MINING Co.

Mailing Address P.O. DRAWER PMC PRICE, UT 84501

State Permit No. ACT/007/006

Utah Coal Mining and Reclamation Act, Section 40-10-1 et. seq., Utah Code Annotated (1953):

Notice of Violation No. N 83-4-7-3 Y TV dated AUG 4, 1983.

Cessation Order No. C _____ Y TV dated _____, 19____.

Violation No. 1 is hereby Terminated _____ Vacated because:

Violation No. 2 is hereby Terminated _____ Vacated because:

Violation No. _____ is hereby _____ Terminated _____ Vacated because:

Date of Service Nov 1, 1983 David Loe #4
Signature of Authorized Representative

Time of Service or Mailing 8:30 a.m. _____ p.m. DAVID LOE #4
Name and I.D. No.