



0078

STATE OF UTAH
NATURAL RESOURCES & ENERGY
Oil, Gas & Mining

Scott M. Matheson, Governor
Temple A. Reynolds, Executive Director
Cleon B. Feight, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

April 22, 1983

Mr. Ben Grimes
Engineering and Reclamation Specialist
Plateau Mining Company
P.O. Box PMC
Price, Utah 84501

RE: Drainage Delineation at
the Trash Bin
ACT/007/006
Folder No. 7
Carbon County, Utah

Dear Ben:

This letter is to confirm our telephone conversation on April 22, 1983. As was stated, Plateau Mining Company will be responsible for drainage at the Lion Deck Refuse Bin. As long as disturbed area drainage remains separate from the haul road, with a clear delineation of the two, there will be no change required in drainage of the haul road.

It should be noted that Plateau Mining Company is responsible for Part 817.45 of the regulations which states that appropriate sediment control measures shall be maintained to prevent to the extent possible additional contributions of sediment to stream flow or to runoff outside the permit area. If drainage problems, directly due to the operation of the trash areas, as opposed to vehicle traffic, become evident then the area will need to be readdressed. If you have any questions don't hesitate to call myself or Joe Helfrich of the Division.

Sincerely,

BARTON D. KALE
FIELD SPECIALIST

BDK/lm

cc: Dave Lof, DOGM
Joe Helfrich, DOGM