

October 2, 1986

TO: File

FROM: Tom Munson, Reclamation Hydrologist *TM*

RE: Tipple Yard Area, Drainage Modifications, Plateau Mining Company, Star Point Mine, ACT/007/006-86A, Folder No. 3, Carbon County, Utah

The operator has submitted responses to a letter from the Division dated June 17, 1986, concerning the Tipple Yard Area Drainage Plan. Plateau's response was received by the Division on September 15, 1986. Plateau has adequately addressed all of the Division's concerns except for concern No. 5. The applicant has not presented any cross sections or detailed information on the catch basin design prior to the inlet B-4, as well as the proposed catch basin between culverts B-4 and B-5.

In personal conversations with Mr. Ben Grimes on September 29, 1986, Mr. Grimes committed to addressing this concern by putting together a written description of these small sediment traps, giving dimensions and materials used in construction. Since these are not sediment ponds or detention ponds, but small clean-out ponds used to capture debris prior to culvert inlets, they will be field fit during construction.

djh

cc: J. Whitehead
W. Hedberg
P. Ralphs
9486R/35