



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

August 30, 1988

TO: John Whitehead, Permit Supervisor

FROM: Tom Munson, Reclamation Hydrologist *TM*

RE: Stipulation Response, UMC 817.43(1), Cyprus-Plateau Mining Company, Starpoint Mine, ACT/007/006, Folder #2, Carbon County, Utah

Synopsis

The operator was asked to address and incorporate the appropriate changes into the PAP for culvert protection measures based on a June 7, 1988 field inspection.

Analysis

The operator has adequately addressed the concerns spelled out in the Division's June 10, 1988 letter and memo, although two culverts were not mentioned. Culvert No. 14 apparently does not exist - an error on the part of the Division. Culvert #67 was ignored by the operator, but it is currently not a problem and therefore will not need any protection unless a problem becomes apparent.

Recommendation

Approve and remove Stipulation UMC 817.43(1). Request for insertion into the PAP, the appropriate copies of Map 42.

djh
WP+/15