

0009



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

October 16, 1989

Mr. Benjamin Grimes  
Environmental Coordinator  
Cyprus-Plateau Mining Company  
P. O. Drawer P M C  
Price, Utah 84501

Dear Mr. Grimes:

Re: Identification of Permit Application Package Defects, UMC 784.23(b)(3) and UMC 784.13(b)(3), Cyprus-Plateau Mining Company, Starpoint Mines, ACT/007/006, Folder #2, Carbon County, Utah

Enclosed is a Technical Memorandum that describes several deficiencies in the approved Permit Application Package (PAP). Please provide, by no later than November 3, 1989, seven copies of the following materials:

1. Revised Map 44, Sheets F-12 and G-12; and
2. Copies of Map 47, Sheet E-13 and Map 71.

Sincerely,

A handwritten signature in cursive script that reads "Richard V. Smith".

Richard V. Smith  
Permit Supervisor

djh  
Enclosure  
cc: P. Grubaugh-Littig, DOGM  
W. Warmack, DOGM  
AT64/117



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangert  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

October 12, 1989

TO: Richard V. Smith, Permit Supervisor  
FROM: Pamela Grubaugh-Littig, Reclamation Engineer *pagl*  
RE: Permit Defect-UMC 784.23(b)(3) and UMC 784.13(b)(3).  
Cyprus-Plateau Mining Company, Starpoint Mine, ACT/007/006,  
Folder #4, Carbon County, Utah

## Synopsis and Analysis

Upon review of the disturbed or bonded areas for the Starpoint Mine, some deficiencies in the surface facilities maps were noted. The bonded areas are not found on Map 44, Sheets F-12 and G-12.

Additionally, during a review of the permit, Map 47, Post Disturbance Topography and Cross-Sections, Sheet E-13 was missing, as well as Map 71, Mine Permit Area.

## Recommendation

The applicant must add the reclamation bonded area to the legend and delineate appropriately on Map 44, Sheets F-12 and G-12.

Map 47, Sheet E-13 and Map 71 must be submitted.

djh  
AT45/96