

0023



12/00/006 #2
Cyprus Plateau Mining Corporation
P.O. Drawer PMC
Price, Utah 84501
(801) 637-2875

August 31, 1992

RECEIVED

SEP 02 1992

DIVISION OF
OIL GAS & MINING

Ms. Pamela Grubaugh-Littig
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Ms. Littig,

Re: Ditch 51 Riprap Lining - Request For Extension

We have attempted to complete the lining of ditch 51 by August 31 as required by your letter of August 7 however, we have been unable to acquire riprap of the proper size to complete the job. We have ordered the riprap from a local contractor but, he has had to set up a special crusher and screening equipment to make the rock. It is very difficult to find rock of the proper size in the area. The local contractors make only rounded rock, what they call "hill run" rock which is simply sandstone cobble rock comprised of rounded rock only. This rock is not suitable for ditch lining because it washes away with runoff; angular rock is necessary to lock into position so runoff does not pick it up and roll it down the ditch.

This letter is a request for an extension of time to complete the work. We would like to have until October 10 to complete the job.

Respectfully,

A handwritten signature in black ink, appearing to read 'Ben Grimes'.

Ben Grimes
Sr. Environmental Engineer

cc: John Borla
Mike Kelley
Ben Blackburn
Ralph Moosman

File: ENV 2-5-2-16-44
Chrono: BG920822