



**CYPRUS PLATEAU  
MINING CORPORATION**  
A Cyprus Amax Company

Cyrus Plateau Mining Corporation  
Post Office Drawer PMC  
Price, Utah 84501  
(801) 637-2875

October 29, 1997

Mr. Dick Manus  
Bureau of Land Management  
Price River Resource Area Office  
125 South, 600 West  
P.O. Box 7004  
Price, Utah 84501

SR / PR REC - OCT 29 1997

RE: Abandonment of Longwall Equipment Starpoint No. 2 Mine

Dear Mr. Manus:

More clarification was requested from your office concerning the amount of petroleum fluids normally present in the longwall system. A list of equipment to be left in place and the type of fluid contained follows:


Item of Equipment	Status	Type of Fluid	Normal Capacity
Head drive 650 fluid coupler for face conveyor (gearbox removed)	Will be drained	Dexron II ATF	12 gallons
Tail drive face conveyor	Recovered		
Stage Loader 487 fluid coupler	Will be drained	Dexron II ATF	5 gallons
Stage Loader Gearbox	Will be drained	Century PowerGear 150 320+	8 gallons
Crusher 487 fluid Coupler	Will be drained	Dexron II ATF	5 gallons
Crusher Gearbox	Will be drained	Century PowerGear 150 320+	6.5 gallons
Shearer Ranging Arms (2)	Will be drained	Century PowerGear 150 320+	24 gallons

Shearer Haulage gearboxes (2)	Will be drained	Century PowerGear 150 320+	30 gallons
Shearer Hydraulics	Will be drained	Chevron 150 68	55 gallons (max. estimate)
Shields	Ran with water only last 3 days	MSDS Sheet previously provided	2% to 5% of water for shields

The fluids to be removed from the equipment will be properly disposed.

Should any questions arise, contact Johnny Pappas at 636 2289 or me at 472 0475 after November 4, 1997.

Sincerely,



Tom Hurst  
Mining Engineer

- c. Two, BLM  
Art Palm  
Johnny Pappas  
Jack Trackemas

File Gov. 1.6.3