

## 2002 Annual Report Review

**Permittee:** Plateau Mining Corporation  
**Mine Name:** Star Point Mine  
**Permit Number:** C/007/006  
**Date Report Received:** March 13, 2003

	<b>Date Completed ▼</b>
<b>Assigned Reviewers:</b> <u>Karl R. Houskeeper, Inspector/Engineer</u>	<u>April 17, 2003</u>
<u>Jeriann Ernsten, Biologist</u>	<u>July 29, 2003</u>
<u>Dave Darby, Hydrologist</u>	<u>June 12, 2003</u>

**Instructions:** The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine Internal File.

**Assignments:**

**Inspectors:** Review each cover sheet, AVS Legal/Financial, Mine Sequence Maps.  
**Hydrologists:** Review Water Monitoring Data, Precipitation and Climatological Data, Non-Coal Waste  
**Biologists:** Review Vegetation/Revegetation Success Monitoring, Raptor Survey  
**Engineers:** Review Subsidence Monitoring Data, Annual Impoundment Certification, Annual Overburden, Spoils, Refuse, Floor, etc.

SECTIONS TO REVIEW	SUBMITTED		FINDINGS
	YES	NO	
Cover Sheet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Cover sheet was included.
AVS; Legal/ Financial Update	<input checked="" type="checkbox"/>	<input type="checkbox"/>	A copy of the State of Utah, Department of Commerce change form was submitted in the annual report. This form shows that J.M. DeMichiei has been removed as President of Plateau Mining Corporation and that T. J. Lien is now the acting President of Plateau Mining Corporation. This change was received by the Department of Commerce on August 20, 2002. This information will be coordinated with Division personnel to make sure that the AVS system reflects the change.
Mine Sequence Map	<input type="checkbox"/>	<input checked="" type="checkbox"/>	The mine is in final reclamation.
Water Monitoring Data	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Submitted in database
Precipitation & Climatological Data	<input checked="" type="checkbox"/>	<input type="checkbox"/>	In MRP.
Non-Coal Waste report	<input checked="" type="checkbox"/>	<input type="checkbox"/>	None produced. Mine is in reclamation.

## 2002 Annual Report Review

SECTIONS TO REVIEW	SUBMITTED		FINDINGS
	YES	NO	
Subsidence Monitoring Data	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<p>The subsidence monitoring report indicates that little or no change in 2002.</p> <p>Bruce Ware at the request of Johnny Pappas reviewed his notes relative to a subsidence crack near G 102. This point (G 102) was established July 30, 1996. Mr. Ware noticed a visible crack on October 4, 1997 at G102 and a crack 750 feet south of G 102 at G100. The crack at G 102 was also noted on September 11, 1999, and August 11, 2000. Mr. Ware stated that "this crack has not changed".</p> <p>The Permittee indicates that an amendment to the Division will be submitted that shows subsidence has substantially ceased and that subsidence monitoring will not be conducted in the future.</p>
Annual Impoundment Certification	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<p>The annual report contains a P.E. certified statement that ponds 5, 6, and 9 were inspected. All embankments appear stable with no apparent structural weakness or hazardous conditions. The report also states that ponds 1, 2, 4, and 7 were removed during the reclamation activities of 2002. The report was certified on March 5, 2003.</p>
Annual Overburden, Spoil, Refuse, Floor, etc.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<p>The annual report contains first, second, third, and fourth quarter 2002 refuse pile certifications. The certification dates of these inspections are March 3, 2002, May 30, 2002, September 24, 2002, and December 04, 2002 respectively. No problems were noted during any of the inspections.</p>
Vegetation Data	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<p>Not required or submitted as indicated in Annual Report 2002 cover sheet.</p>

## 2002 Annual Report Review

SECTIONS TO REVIEW	SUBMITTED		FINDINGS
	YES	NO	
Revegetation Success Monitoring	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<p>Not required or submitted as indicated in Annual Report 2002 cover sheet.</p> <p>Star Point Mine reclaimed the following areas in 2002:            1) 25 .5 acres of Mountain Grasslands associated with the Lions Deck and Pond 1 Areas            2) 28 .0 acres of Sagebrush lands associated with the Overland Conveyor and Main Channel Areas.</p> <p>These sites were prepared, seeded, and planted with transplants. Certain areas planned for revegetation were not completed. The Permittee plans to complete the revegetation project in 2003.</p> <p>The Permittee plans to monitor, qualitatively and quantitatively, the revegetated areas. Annual reports beginning from 2003 through bond release will include monitoring results and analysis. The 2003 Annual Report will cover results from the qualitative monitoring.</p>
Raptor Survey	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Not required or submitted as indicated in Annual Report 2002 cover sheet.
Other Information	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Required as indicated in Annual Report 2002 cover sheet, but not submitted.

O:\007006.STP\FINAL\AR\_2002.doc