

0004.

October 16, 1979

Inspection Memo  
to Coal File:

RE: <sup>side</sup>Sunnydale Mine  
Kaiser Steel Corporation  
ACT/007/007

The <sup>side</sup>Sunnydale Coal Mine was given a follow-up inspection on October 10, 1979, by Office of Surface Mining inspector, Ray Lewis, and State Division of Oil, Gas and Mining personnel Mary Ann Wright, Joe Helfrich and Doug Stewart.

John Huefner, Professional Engineer, showed us the new sedimentation pond consisting of approximately 1.8 acre feet.

1. 30 CFR 717.15 Disposal of excess earth materials.  
It appeared, as John pointed out, that the above violation was now abated (1 year study proposal).
2. 30 CFR 717.12 Failure to post signs and markers.  
John showed that all necessary signs were installed in compliance with violation issued on May 10, 1979.
3. 30 CFR 717.14 Failure to grade road and surface work areas.  
The areas of: twin shaft portal, upper pad and new change-bathhouse had been graded and hi-wall had been terraced and awaiting revegetation.

The lower slurry pond, where mining of dry material is going on by a private mining company (Sunnydale Corporation), was discussed to some extent as to the need of reseeding the ponds on the out-facing slopes.

DOUG STEWART   
RECLAMATION OFFICER

cc: O.S.M., Region V

Note: For statistics see Convulsion Canyon Mine memo dated October 16, 1979.

DS/te